

DIY Zoning: Old News (2001-2007)

Table of contents

| | |
|----------------------------|---|
| 1 2007..... | 4 |
| 1.1 May 1 2007..... | 4 |
| 1.2 April 27 2007..... | 4 |
| 2 2006..... | 4 |
| 2.1 August 31 2006..... | 4 |
| 2.2 February 6 2006..... | 4 |
| 2.3 February 1 2006..... | 4 |
| 3 2005..... | 5 |
| 3.1 July 28 2005..... | 5 |
| 3.2 July 23 2005..... | 5 |
| 3.3 July 16 2005..... | 5 |
| 3.4 May 31 2005..... | 6 |
| 3.5 March 15 2005..... | 6 |
| 3.6 February 24 2005..... | 6 |
| 3.7 January 11 2005..... | 6 |
| 3.8 January 6 2005..... | 6 |
| 4 2004..... | 6 |
| 4.1 October 11 2004..... | 6 |
| 4.2 October 9 2004..... | 6 |
| 4.3 September 30 2004..... | 7 |
| 4.4 September 29 2004..... | 7 |
| 4.5 September 24 2004..... | 7 |
| 4.6 September 17 2004..... | 7 |
| 4.7 September 16 2004..... | 7 |

| | |
|--------------------------------------|----|
| 4.8 September 3 2004..... | 8 |
| 4.9 August 31 2004..... | 8 |
| 4.10 July 28 2004..... | 8 |
| 4.11 July 5 2004..... | 8 |
| 4.12 July 2 2004..... | 9 |
| 4.13 June 29 2004..... | 9 |
| 4.14 June 24 2004..... | 9 |
| 4.15 June 23 2004..... | 9 |
| 4.16 June 8 2004..... | 9 |
| 4.17 April 19 2004..... | 10 |
| 4.18 March 24 2004..... | 10 |
| 4.19 March 23 2004..... | 10 |
| 4.20 March 22 2004..... | 10 |
| 4.21 March 5 2004..... | 10 |
| 4.22 March 3 2004..... | 11 |
| 4.23 March 1 2004..... | 11 |
| 4.24 February 29 2004, take two..... | 12 |
| 4.25 February 29 2004..... | 12 |
| 4.26 February 26 2004..... | 12 |
| 4.27 February 25 2004..... | 13 |
| 4.28 February 23 2004..... | 14 |
| 4.29 January 29 2004..... | 14 |
| 4.30 January 25 2004..... | 14 |
| 4.31 January 24 2004..... | 14 |
| 4.32 January 21 2004..... | 14 |
| 4.33 January 20 2004..... | 15 |
| 4.34 January 13 2004..... | 15 |
| 5 2003..... | 15 |
| 5.1 December 27 2003..... | 15 |

| | |
|-------------------------|----|
| 5.2 August 20 2003..... | 15 |
| 5.3 August 19 2003..... | 15 |
| 5.4 August 17 2003..... | 16 |
| 5.5 August 8 2003..... | 16 |
| 5.6 June 26 2003..... | 16 |
| 5.7 May 11 2003..... | 16 |
| 5.8 May 1 2003..... | 16 |
| 6 2002..... | 16 |
| 6.1 July 29 2002..... | 16 |
| 6.2 July 9 2002..... | 16 |
| 6.3 July 8 2002..... | 16 |
| 6.4 July 1 2002..... | 17 |
| 6.5 June 26 2002..... | 17 |
| 6.6 June 18 2002..... | 17 |
| 6.7 May 1 2002..... | 17 |
| 6.8 January 2002..... | 17 |
| 7 2001..... | 17 |
| 7.1 December 2001..... | 17 |
| 7.2 September 2001..... | 17 |

1. 2007

1.1. May 1 2007

DZ made [Makezine](#).

1.2. April 27 2007

DZ made [Hack A Day](#).

2. 2006

2.1. August 31 2006

Another round of performance optimization underway. [OWAPI changes](#) continue, mostly stability updates. Major improvements in PID controller and display implementation, with speed gains over 100%. All of the above translates into much less CPU intensive operation.

Oh, and RxTx transition, as well as JDK 1.5 transition, were noneventful. Guess it's time now to merge the `JDK_1.5` branch back into the main trunk.

2.2. February 6 2006

Transition to [RxTx](#) 2.1-7 (the one that uses `gnu.io` instead of `javax.comm`) seems to have gone smoothly. Uptime is getting close to 24 hours now, which, given the previous all-or-nothing upgrade history, is a good sign.

Now, let me take care of changing all the places in the documentation where the version of RxTx is mentioned...

2.3. February 1 2006

The [RxTx](#) is the hot topic again... I barely had time to enjoy RxTx working flawlessly with JDK 1.5, but then Sun came and broked it again, releasing 3.0 version of [CommAPI](#). Not too many people got upset right away, because the only ones that noticed it would be newcomers that don't have a copy of the old `comm.jar` (that's right, you can't legally download it anymore).

Well, the time has come to finally switch to `gnu.io` namespace. Stay tuned.

3. 2005

3.1. July 28 2005

[v.2](#) is coming. Along with planned architecture changes, features long requested are being implemented, the first of them being the RRD logger that doesn't break when a new data source is added.

[xAP](#) and [xPL](#) protocol support should be usable by now, too. The actual packet format may differ from the documented one (this is a work in progress), but it's more or less self-explanatory.

3.2. July 23 2005

3.2.1. JDK 1.5 Transition

DZ is feeling well on JDK 1.5.0_04. The version of the code without 1.5 specific features ran for 12 days with no problems, and now the code that had been enhanced with 1.5 features (starting with generics, but the rest (concurrent, I/O, etc.) will follow) runs just as smooth.

Memory consumption has increased, but it seems that it's mostly due to shared JVM core size increase - DZ [DAC](#) runs perfectly even if given as little as `-Xms2m -Xmx2m` memory.

Those willing to be a guinea pig are welcome to get the `JDK_1.5` branch from the [CVS](#).

3.2.2. xAP/xPL Packet Extension

A timestamp was added to [xAP](#) and [xPL](#) producers. The format is ISO 8601 `yyyy-MM-dd 'T' HH:mm:ss .SSSZ`.

Note:

This breaks the xPL's `SENSOR.BASIC` schema (for DZ DAC output), but a) it's configurable, you can shut it off; b) it is well worth it, in my opinion, to extend the `SENSOR.BASIC` to include the timestamp to avoid ambiguity in time-critical applications, which DZ is.

3.3. July 16 2005

Finally, [RxTx](#) seems to have caught up with stability issues, and the current version from CVS works with JDK 1.5.3_04 with uptime exceeding a week now, [here](#).

This brings up two issues:

- bring DZ up to date with JDK 1.5 features (I was putting this off for a long time because RxTx didn't work with JDK 1.5 for more than a few seconds);
- finish the introduction of a distributed logging daemon support with the logging module pluggable not just into the [DAC](#), but located anywhere (including a completely standalone module).

In related news, Apple has recently renamed the network protocol formerly known as [Rendezvous](#) to [Bonjour](#), at the same time extending its functionality - another action item. Draft support for this protocol is already a part of DZ, now I have to make it functional.

3.4. May 31 2005

A package with a [serial](#) and [USB](#) controllers that came as a donation from [Parallax, Inc.](#) is on my desk. Details [here](#).

3.5. March 15 2005

Replaced [jUSB](#) with [javax.usb](#). This was done for [Servomaster](#) back in October 2004, so far, there were no complaints - time to finalize the changes.

3.6. February 24 2005

Added [xAP](#) and [xPL](#) home automation protocol support modules. Neither has yet been tested with a live xAP/xPL application - waiting for Chris "madmax" to verify the implementation.

3.7. January 11 2005

[Pololu Corporation](#) has generously donated a [16-Servo USB Controller](#). Support is coming - keep watching [Servomaster](#) project pages.

3.8. January 6 2005

Fixed some obsolete and invalid links.

4. 2004

4.1. October 11 2004

Documented [changes to Dallas OWAPI](#).

4.2. October 9 2004

Received the 1-Wire® USB Adapter sample from Dallas. Support is coming.

4.3. September 30 2004

<rant>

O [JavaSpaces](#), where art though?

</rant>

As DZ progresses, it ages. Original concept stays, but it becomes overwhelmed with details, most of which don't fit into the architecture, and while it is still sound and relatively future-proof, the need to simplify and optimize the architecture becomes more and more nagging.

One good concept is the aforementioned [JavaSpaces](#). Unfortunately, it is a stillborn child because it depends on Sun's [Jini](#) technology, which didn't deliver what it promised, and, therefore, is basically dead.

Well, since the [JavaSpaces implementation](#) can't be used within the constraints imposed on DZ by its environment, at least the original idea ([ComponentBus](#)) can be, and will be.

It will be a while until the new architecture becomes the reality, meanwhile, [v.2 notes](#) chapter will accumulate notes to myself and later will be used as a requirements document for the new architecture.

4.4. September 29 2004

Added a chapter on [Fault Tolerance](#).

4.5. September 24 2004

0.1p7dev3 release is [out](#). This release introduces support for multiple logical devices per one physical 1-Wire® device in general and for [TAI8540A](#) humidity sensor in particular.

Necessarily, DAC2CORE protocol has been changed. Backward compatibility couldn't be maintained, so you'll have to upgrade your configuration - see [release notes](#).

4.6. September 17 2004

Started working on changing the DAC2CORE [protocols](#) to support pressure and humidity sensors.

4.7. September 16 2004

Added DAC support for multiple logical 1-Wire® devices per single physical device. Such is the case with at least DS2438 which can be used as a temperature container and humidity container.

4.8. September 3 2004

Added initial support for [AAG Electronica TAI8540A](#) humidity sensor.

4.9. August 31 2004

August had been slow.

Not only a [certain event](#) occurred, which definitely slowed down everybody concerned, but some other things happened as well.

One of them, quite catastrophic, was a workstation rebuild. RedHat9 had reached end-of-life and had to be replaced, so couple of weeks were spent on selecting a new distribution. Eventually, Mandrake 10 was installed as a decent compromise between being fresh enough, stable enough, and usable enough. RedHat's successor, Fedora Core, doesn't impress much. SuSe 9.1 out-of-the-box lacks development tools, and there's no GNOME, of which I'm fond (for lack of an old good FVWM). [RxTx](#) 2.x still dumps core, and I don't know yet if 1.4-15 still works.

Well, "software rot" is a known phenomenon, and it'll take some time to sort out the consequences, most important of which is: [jUSB](#) stopped compiling because of the kernel version change (still works, though). Since a USB servo controller is the best supported device at this point, this definitely poses a problem that needs fixing ASAP.

Another thing worth mentioning is that [AAG Electronica](#) had generously donated a [pressure sensor](#) and a [humidity sensor](#), which allows to start working on optimizing [static pressure control](#).

4.10. July 28 2004

0.1p7dev2 release is [out](#). This is a development release intended to serve as a test drive for a [CORE configuration wizard](#). See [Release Notes](#) section for more information.

4.11. July 5 2004

0.1p7dev1 release is [out](#). This is a development release intended to serve as a test drive for a

[DAC configuration wizard](#). See [Release Notes](#) section for more information.

4.12. July 2 2004

The current CVS trunk contains a working [DAC](#) configuration wizard (the GUI still needs to be polished, but it is able to produce a valid configuration). The shell script for it is at `${install_prefix}/bin/dz_dac_wizard`.

[JRobin](#) was upgraded from 1.2.2 to 1.3.1. Performance increase is about tenfold. However, it is possible that there's a bottleneck in DZ RRD regeneration code somewhere - JRobin authors (who's using DZ raw trace as a benchmark data sample) reports much faster times than I was able to achieve. I believe him.

4.13. June 29 2004

0.1p6 release is [out](#). See [Release Notes](#) section for more information. One item worth mentioning here, though, is: PnP is now operational.

4.14. June 24 2004

Followup to DS18B20 story: I completely forgot that there are other devices that implement `TemperatureContainer`. Just in case, all of them were added (for compatibility), even though not all of them were created equal (see notes in [Parts List](#) section).

Also, support for DS2408 and DS2405 (obsolete, but oh well, let it be) was added, as well as support for DS2890 digital potentiometer.

TODO: Figure out how do switch containers that aren't DS2405...DS2409 interfere with the DAC operation.

4.15. June 23 2004

Ouch! Turns out that DS18**B**20 doesn't work, as opposed to DS18**S**20 (a.k.a. DS1920). [Bug #978381](#) had been created, and a DS18B20 sample ordered to verify the fix. The root cause is funny: these two, even though the names are similar, belong to different container families.

4.16. June 8 2004

Absolutely frustrated with attempt to make any version of [RxTx](#) compile on any of my boxes, started a replacement driver based on [OWFS](#). Initial draft seems quite a bit slower than the OWAPI based code, mostly due to the fact that the whole directory subtree has to be traversed all the time, even the empty subdirectories, but since there's a high degree of

cooperation from the OWFS development team, I guess, there will be improvement. Also, as a side effect, 1-Wire® USB adapter will be available.

Or someone fixes RxTx, which I gave up on.

4.17. April 19 2004

Added schematics and PCB layout for 1-Wire temperature sensors and DS2890 based servo controller (generously contributed by Nic van der Walt) to the [Sensor Network](#) page.

4.18. March 24 2004

[JRobin](#) author, Sasa Markovic, contacted me a while ago with questions regarding JRobin performance (see [March 5](#) notes). Turns out, DZ code has a bottleneck somewhere, so JRobin is not THAT slow, but anyway, he says that my criticism motivated him to stress test JRobin, and as a result, JRobin is about 20 times faster as of release 1.3.1 (soon to be released).

4.19. March 23 2004

The new site layout problems are eventually fixed (hopefully), and it is (again, hopefully) now ready for public consumption.

Note:

Nevertheless, the old site will still be available (at least, for a while) at <http://diy-zoning.sourceforge.net/old/>, just in case I forgot something.

4.20. March 22 2004

Sic transit gloria mundi, take 2 (site access statistics illustrating "Slashdot Effect"):

Makes interesting comparison with the first coming, two years ago:

4.21. March 5 2004

JRobin is not just slow, it's SLOW. It takes up to 15 second to create the set of graphs RRDTool creates in about 2 seconds. It takes over 100 seconds to create a standard RRD for 8 sensors, something that is negligible with RRDTool. The RRD regeneration script gave me something of a shock when I realized that `rrdupdate` manages to get called more than 500 times per second on a trace file containing 567,686 (that's five hundred sixty seven thousand

and six hundred eighty six) entries (on Athlon XP 2100+ box with 512MB DDR memory). Sketch of an RRD regeneration process with JRobin shows 2 records per second. I guess re-rendering that big trace file of mine is out of question, since it's going to take over three days.

Oh well, maybe I didn't do something right.

In any case, some creative thinking about queueing the incoming data and synchronizing RRD creation, updates and regeneration will be required to make it work seamlessly (as in "fast enough and so different threads don't stand in each other's way").

Still, JRobin may be an acceptable solution since the RRD database creation and regeneration doesn't happen that often - just be careful when you add a new sensor after your sensor network's been up for a long time.

The verdict stays: both JRobin and RRDTool will be supported, the former for beginners, the latter for advanced users. What a disappointment.

4.22. March 3 2004

Implemented native Java RRD database driver based on [JRobin](#). Well, my hopes were high, but the reality turned out to be bleaker than the dreams.

Of course, it is very, very convenient not to have a platform dependent tool, which, in addition to that, doesn't come in RPM and has to be installed manually (all right, it's not a problem for me, but what about the end users?).

But, there is a price to be paid.

First of all, JRobin RRD is not binary compatible with RRDTool RRD. Sure, platform independent JRobin RRD is better, but it also means incompatibility with RRDTool. Not good, especially if you keep in mind the next paragraph.

Even though JRobin seems to support more advanced graph generation features, RRDTool has a significant advantage - it is scriptable. You don't have to modify Java code and recompile it every time you want to change the way the graphs look.

The verdict: For now, both RRDTool and JRobin based loggers will be supported. For beginners, seamless JRobin. For advanced users, whatever they choose. They can take care of themselves.

4.23. March 1 2004

UPnP? Who needs UPnP?

Not so fast...

All right, it seems that UPnP is at least somewhat supported in the HVAC world (at least Trane Tracer, mentioned [here](#), is UPnP compliant and proud of it). However, deeper analysis shows that UPnP has some serious problems, not just implementation, but architectural problems: [this article](#) was written by UPnP network architect and SSDP lead author. Not a pretty sight.

On the other hand, there's this immortal phrase coined by one of my friends: "It sucks, but it's the best". Indeed, it seems that at least the UPnP *promise* is exactly what's needed to make the integration seamless. [Jini](#) seems to be DOA, it's too heavyweight, and locked in into Java (which I don't appreciate even though Java is the current implementation language), and others ([Apple Rendezvous](#) and [Salutation](#), to mention a few) seem weird (don't hasten to judge me, though, it takes time to learn all these things).

All right, so the bottomline (for now) is: it took me 10 minutes to write a simple multicast socket broadcaster/listener pair, and it'll take a week to polish it up, and this is what will be used in the 0.2p0 release. In the future, either the necessity will show itself, or a new protocol will emerge - then, let's talk again.

Note:

Hmm... This page starts looking like a blog now... I wonder if SourceForge going to offer blog support anytime soon?

4.24. February 29 2004, take two

Uh-oh... [Slashdotted](#) again :) 76,826 visits in a day - not bad at all.

4.25. February 29 2004

What a can of worms I've just opened... I regret not seeing the [HVAC V1.0 Standardized DCP](#) specification the day it was released..

Bottomline: I'm not sure it would be reasonable to make DZ support [Universal Plug-n-Play](#) specification right away (just because this will take quite a bit of effort, and it is an intimidating task on its own), but this is definitely something to keep in mind.

FIXME (VT):

Don't forget to get back to this later.

4.26. February 26 2004

Usability first, everything else be damned... Working on RRD database autogeneration. From now on, if only `rrdtool` is found on the system, the RRD database will be created and graphs will be drawn automatically. No more hacking RRD creation and graphing scripts.

(about 20 hours later)

I'll be damned, Eric Raymond didn't waste his time. Since I do have delusions of grandeur (What? You didn't notice?), I can afford to say "great minds work alike"... As I was struggling with RRD autogeneration, he was writing a nice article about clueless people like myself: [The Luxury of Ignorance: An Open-Source Horror Story](#). Well, just go and read it. Meanwhile, I'm working on improving usability.

4.27. February 25 2004

A little search engine saga...

DZ is #2 on brand new [Yahoo](#) search engine, right after Honeywell...

I looked at that, and out of curiosity, decided to do some ego surfing and see where DZ stands with other search engines. Well, here are the ones I tried (in order [Google](#) gave them to me, plus the results of "search engine" Google query):

- [AltaVista](#)
- [Ask Jeeves](#)
- [Teoma](#)
- [WiseNut](#)
- [Gigablast](#)
- [Scrub The Web](#)
- [TrueSearch](#)
- [Search Hippo](#)
- [Walhello](#)
- [Deepindex](#)
- [Wotbox](#)
- [Dogpile](#)
- [Lycos](#)
- [Excite](#)
- [AlltheWeb](#)
- [WebCrawler](#)

Well, turns out that most of them have DZ on the first page, some of them list it as #2, some don't know about it at all (even with a direct search). It's evident that there are fewer search engines than there are search sites - results on different sites look alarmingly identical. Quality of the search is vastly different - some of the sites listed in the Google category aren't really

search engines, but retailer portals. However (and this is the reason for the results of this dubious exercise are recorded here), *some of the obscure and little-known search engines may present a different point of view at the subject, and they'll give you links that you would never find on Google or Yahoo.*

4.28. February 23 2004

Communication between DAC, CORE and VIEW is now encrypted using SSL.

4.29. January 29 2004

A rough draft of HOWTO is now available.

Note:

The HOWTO guide was obsoleted by the site redesign - the whole site now is one big HOWTO.

4.30. January 25 2004

[Release Notes](#) page was created, with upcoming 0.2p0 changes summary. Navbar has to be changed when the time allows.

4.31. January 24 2004

[Bug #734976](#) has been fixed.

[Bug #866567](#) has been fixed.

The DAC, which now runs on OWAPI 1.00 with RxTx 1.4.15, seems to be stable - not a single core dump, and uptime was reaching two days.

4.32. January 21 2004

OWAPI 1.00 migration turned out to be tougher than expected. RxTx 2.x is nowhere near as stable as 1.4.15 was - with 1.4.15, uptime was reaching months, and the reason for the termination was never a JVM core dump, but either a power failure, or normal development restart. With RxTx 2.1, uptime barely reaches a few minutes.

Consequently, RxTx 1.4.15 was reinstated, and OWAPI 1.00 code was backported to using `javax.comm` - good thing that the only change required (at least on the surface) was to replace the import statement.

To be continued...

4.33. January 20 2004

[Bug #864816](#) is gone for good, hopefully. Indeed, it required a redesign - all the signal path from the sensor to the thermostat to the zone controller and beyond had to be modified. But the effort was worth it - right now, a partial or complete sensor failure will not cause any undesirable behavior - if a zone sensor dies, the damper for that zone will just stay open, and if all the sensors die, the system is gracefully shut down.

Down the same road, the next target is upgrade to [OWAPI 1.00](#) (hope to fix [bug #724534](#) and suchlike atrocities). Unfortunately, this will cause major headache because in order to do so [RxTx](#) has to be upgraded, which in turn requires autoconf/automake upgrade and most probably breaks ServoMaster (which will also require upgrade).

Oh well, it was a good time to catch up with the DalSemi folks and fix their bugs anyway.

4.34. January 13 2004

Bug hunt for [bug #864816](#) has started. Some redesign will be required to make the solution elegant, so the code is branched out. The branch name is `Bug_864816`.

5. 2003

5.1. December 27 2003

The project is being revised and put to life, thanks to Tim Small - the first person to actually make it work. I can't let him down ;)

Unfortunate side effect - turned out that SourceForge changed their server setup in such a way that it is not possible to `scp (1)` stuff to or from the shell server anymore. Javadocs will not be updated until I figure out a way to bypass this limitation.

5.2. August 20 2003

All the stuff that was served from `freehold.crocodile.org` had to be moved to another port. It's available again.

5.3. August 19 2003

I already miss it. The new house has much better HVAC equipment (two variable speed units, one is Trane and other is high-end Lennox), so theoretically everything should be better. In reality, though, once you've tried the zoning system, there's no way back. My

family is complaining again. It's not impossible for me to be eventually allowed to staple the blue CAT-5 cables on the white walls again ;)

5.4. August 17 2003

Today, the system has been shut down after almost two years of seamless operation. Reason for shutdown: relocation.

5.5. August 8 2003

DZ is again #2 on [Google](#) :)

5.6. June 26 2003

Someone had recently brought to my attention that DZ takes a second place after Honeywell on [Google search](#) for "temperature zoning". It was an ego boost all right, but today I've found that it slipped one step down, after a company I've never heard of, [Princeton Air Conditioning, Inc.](#). Oh well...

5.7. May 11 2003

Oops... [HVAC-Talk](#) is expiring threads... Good I have backups. [Updated](#).

5.8. May 1 2003

Over 18 months of uninterrupted service... The system still works in passive mode. Turns out that controlling the A/C wasn't **that** critical, and the system is almost as good without it. [Read more...](#)

6. 2002

6.1. July 29 2002

Access statistics: [Sic transit gloria mundi...](#)

6.2. July 9 2002

This project made [Slashdot](#) ;)

6.3. July 8 2002

Rudimentary TCP client view, able to present the system overview and control the system across the TCP connection, is complete.

6.4. July 1 2002

Rudimentary TCP server view, sufficient to start working on the TCP client view, is complete.

6.5. June 26 2002

The GPL core is operational. Release 0.1p0 is [available for download](#).

6.6. June 18 2002

The GPL onewire_server has replaced the proprietary one. Release 0.1p0 is on its way.

6.7. May 1 2002

DIY Zoning project started.

6.8. January 2002

[Motorized registers](#) are installed, the system is activated in a [passive mode](#).

7. 2001

7.1. December 2001

More sensors installed, now covering all the areas of interest.

7.2. September 2001

The cabling is done, the initial set of sensors is installed. Data acquisition started.